



Terca Brick Maintenance

Cleaning method

The proposed cleaning method consists of regularly (annually) cleaning the façade by means of cleaning. High pressure, under the following conditions:

- Maximum pressure 70 bar = 1000 PSI
- Working with a V-beam and spraying at an angle of 45 degree
- Do not spray perpendicular to the facade because otherwise the dirt will be sprayed into the brick

